MAR 1 6 1983,

Mr. Douglas M. Johnson Environmental Waste Control 1159 Manchester Avenue Wabash, IN 46992



Dear Mr. Johnson:

Re: Disposal of Empty 30-Gallon Cyanide and Dichromate Drums from Johnson Controls, Inc. Goshen, Indiana

This letter acknowledges the request for disposal dated February 9, 1983, from Mr. Stanley D. Leedy, Johnson Controls, Inc.

Approval is hereby granted for disposal of sixty-five 30-gallon empty containers of trace amounts of cyanide and dichromate at the Four-County Landfill, OPP. No. 25-2, Fulton County. The waste is to be disposed of in the separate disposal area of the landfill and covered with a minimum of 12 inches of cover soil by the end of the working day.

The approval is granted subject to the following conditions:

- 1. The generator and/or hauler must contact you to notify you of the time of disposal and conditions of shipment.
- 2. If nuisance or pollution conditions are created, immediate corrective action will be taken by the operator.
- 3. This approval will expire June 1, 1983.

This approval will be revoked if the landfill fails to maintain compliance with 320 IAC 5-1, et seq. (Regulation SPC-18). Any necessary local approval must be obtained from the Fulton County Health Department. The waste must be transported by a hauler who holds a valid permit issued pursuant to 320 IAC 5-10, et seq. (Regulation SPC-17).

If you have any questions, please contact Mr. Ted Warner of the Hazardous Waste Management Branch at 317/633-8525.

Very truly yours,

Ralph C. Pickard Technical Secretary

TW/dw

cc: Stanley D. Leedy

Johnson Controls, Inc.

bcc: Landfill File Approval Book dw 5059m 3/8/83

Johnson Controls. Inc. 1302 East Monroe Street Goshen. IN 46526 Tei 219 533-2111

FEB 9 10 56 AM '83



Indiana State Board of Health Div. of Land Pollution Control 1330 West Michigan Street Indianapolis, IN 46206

Dear Mr. Warner:

This letter is written to request permission to dispose of approximately (35) empty 30 gal. cyanide drums and 30 empty 30 gal. dichromate drums in the Four County Landfill at Rochester, Indiana.

The cyanide drums are visually empty and clean, however, trace amounts of granules may be present around the bottom seam. The dichromate drums have a poly liner and would contain small amounts of liquid, however, it would be far less than 1" or .03% of original capacity. The solution originally in these drums is a propitiatory dichromate solution that contains Chromic Acid.

We normally fill these drums with plating waste treatment sludge and then through the Manifest Regulation they are disposed of at Four County Landfill. Due to our use of 55 gal. drums for sludge these 30 gal. drums have accumulated and must be removed from our property.

Thank you very much for your prompt return of my call Wednesday, February 2, 1983. If there are any questions please call Stanley Leedy, Johnson Controls, Inc. 219-533-2111.

Sincerly yours,

JOHNSON CONTROLS, INC.

Star Leedy

Pollution Control Engineer

SDL/bam

Called on 2-14-83